

T ECHNICAL INFORMATION



A1290

January 2014

Subject ▶ Change of Switch

For Models ▶ BDA340, BDA341, BDA350, BDA351, BDF448, BDF458, BHP448, BHP458, BTD134, BTD146, DDF458, LXDT03, LXDT04, LXFD03, LXPH03, XFD03, XPH03

Country ▶ All countries

Description ▶ Switch has been changed to improve the durability.
The wiring and assembling way remain the same.

Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
007	Switch TG573FSB-1 650241-4		1	←	Switch TG573FSB-1 650722-8		1	BTD134, BTD146
007	Switch TG573FSB-2 650660-4		1	←	Switch TG573FSB-2 650723-6		1	LXDT03, LXDT04
006	Switch TG573FSB-3 650682-4		1	←	Switch TG573FSB-3 650724-4		1	BDF448, BDF458, BHP448, BHP458, DDF458, LXFD03, LXPH03
006	Switch TG573FSB-4 650683-2		1	←	Switch TG573FSB-4 650725-2		1	DDF458, LXFD03, LXPH03, XFD03, XPH03
031	Switch unit 638880-0		1	←	Switch unit 632B90-3		1	BDA340, BDA341, BDA350, BDA351
031	Switch unit 638881-8		1	←	Switch unit 632B91-1		1	

Interchangeability mark ;

The arrow ← means that the new part can be substituted for the current.

Implementation

From January 2014 production