

# TECHNICAL INFORMATION



A3606  
February 2014

**Subject** ▶ Change of Rotor

**For Models** ▶ BTD136, BTD147, DTD136, DTD147, LXDT06, XDT06

**Country** ▶ All countries

**Description** ▶ Rotor for repair has been modified to improve the durability against the vibration.  
The shape remains the same.

## Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
006	Rotor 619297-6		1	←	Rotor 619353-2		1	

### Interchangeability mark ;

The arrow ← means that the new part can be substituted for the current.

## Implementation

From January 2014 production