

# TECHNICAL INFORMATION



Y06333  
January 2013

**Subject** ▶ Change of Part name

**For Models** ▶ Makita: BBX7600, BBX7600N, BBX7600G, EK7651HG, PK7650H, PM7650HG  
DOLMAR: PB7600.4, PC7612V, PC7614V  
Others: FLH7500

**Country** ▶ All countries

**Description** ▶ Part name of Oil seal has been changed from “Oil seal (S)” to “Oil sesla 17”.  
The actual part and its part number remain the same.

|        | Model No. | Item No. |
|--------|-----------|----------|
| Makita | BBX7600   | 086      |
|        | BBX7600N  | 086      |
|        | BBX7600G  | 086      |
|        | EK7651HG  | 138      |
|        | PM7650H   | 156      |
|        | PM7650HG  | 156      |
| DOLMAR | PB7600.4  | 086      |
|        | PC7612V   | 138      |
|        | PC7614V   | 138      |
| Others | FLH7500   | 086      |

## Interchangeability(I/C)

| Item No.   | Current part             |  | Q'ty | I/C | New part                |  | Q'ty | Note |
|------------|--------------------------|--|------|-----|-------------------------|--|------|------|
| See below. | Oil seal (S)<br>213599-8 |  | 1    | Yes | Oil seal 17<br>213599-8 |  | 1    |      |

## Implementation

From October 2012 production