

# T ECHNICAL INFORMATION




Y06622  
May 2014

**Subject** ► Change of components of Cylinder block assembly

**For Models** ► DOLMAR: CS-246.4 C, LT-246.4, MH-246.4 D, MH-246.4 DS, MS-246.4 C, MS-246.4 CE, MS-246.4 U, MS-246.4 UE, MS-256.4 C, MS-257.4 C  
Makita: EJ2650LHG, EJ2651WHG, EM2650LH, EM2650LHN, EM2650UH, EM2650UHN, EM2651LH, EM2651UH, EM2652LHN, EN4950H, EN4950HG, EN5550SH, EN5950SH, EN5950SHG, EN7350SH, ER2650LH, EX2650LH, EX2650LHG

**Country** ► All countries

**Description** ► The components of Cylinder block assembly have been changed as drawn below.



## Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
116	Cylinder block assembly 135478-9		1	←	Cylinder block assembly 135478-9		1	The part No. remains the same.
D10	Inc. 117				Inc. 117, 118, 137			

### Interchangeability mark;

The arrow ← means that the new part can be substituted for the current.

## Implementation

Already implemented