





# TECHNICAL INFORMATION



75224  
February 2006

- Subject** ▶ Change of Pin Cap and Shoulder Pin 5
- For Models** ▶ GA7020, GA7020S, GA9020, GA9020S, MT900, MT901, M907, M908, SA7021
- Country** ▶ All countries
- Description** ▶ Pin cap and Shoulder pin 5 have been changed as illustrated below.

	▶ Current	▶ New
Pin Cap	 <p>ø6mm (419133-4)</p>	 <p>ø4mm (416449-8)</p>
Shoulder Pin 5	 <p>ø6mm (256491-5)</p>	 <p>ø4mm (256499-9)</p>

## Interchangeability(I/C)

Item No.	Current part	Q'ty	I/C	New part	Q'ty	Note
001	Pin Cap ----- 419133-4	1	No	Pin Cap ----- 416449-8	1	Interchangeable as a set
GA7020, GA7020S, GA9020, GA9020S, SA7021: 035  MT900, MT901, M907, M908: 032	Shoulder Pin 5 ----- 256491-5	1	No	Shoulder Pin 5 ----- 256499-9	1	

## Implementation

From initial production