


TECHNICAL INFORMATION



65891A

- Subject** ▶ Change of Ball Bearing
- For Models** ▶ GD0800C, GD0810C
- Country** ▶ All Countries
- Description** ▶ Ball Bearing 6001LLB (2 pcs.) has been replaced by Ball Bearing 6001ZZ



Interchangeability(I/C)

| Item No. | Current part | | Q'ty | I/C | New part | | Q'ty | Note |
|----------|----------------------|--|------|-----|---------------------|--|------|------|
| 010 | Ball Bearing 6001LLB | | 2 | ← | Ball Bearing 6001ZZ | | 2 | |
| 019 | 211142-7 | | | | 211148-5 | | | |

Interchangeability mark ;

The arrow ← means that the new part can be substituted for the current.

Implementation

GD0800C: From serial No.10826E (Apr. 2002)

GD0810C: From serial No.7865E (Apr. 2002)