


# T ECHNICAL INFORMATION

- Subject** ▶ Change of the Bolts for Fixing Motor Housing
- For Models** ▶ HK1800, HK1800L, HK1810
- Country** ▶ All countries
- Description** ▶ The bolts in the subject have been changed as illustrated below.



## Interchangeability(I/C)

Item No.	Current part	Q'ty	I/C	New part	Q'ty	Note
HK1800: 060 HK1800L: 043 HK1810: 059	Hex. Socket Head Bolt M6x45 ----- 265923-1	4	No	Hex. Socket Head Bolt M6x45 ----- 266252-5	4	↑ Interchangeable as a set ↓
HK1800: 062 HK1800L: 045 HK1810: 061	Flat Washer 6 941152-7 -----	4		-----		

## Implementation

- HK1800 : From serial No.57187E (Jan.,2000)
- HK1800L: Discontinued since Apr.,1993
- HK1810 : From serial No.61779E (Jan.,2000)