

Subject ▶ Changes on Ball Bearing

For Models ▶ HK1800, HK1800L, HK1810, HK1801L (Power Scraper)

Description ▶ As illustrated below, Ball Bearing 6002LLB has been changed to Ball Bearing 6002LLU for improvement in endurance.

	▶ Current	▶ New
	Ball Bearing 6002LLB (Seal Color: Black)	Ball Bearing 6002LLU (Seal Color: Red.)

Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
16	Ball Bearing 6002LLB 211201-7		1	Yes	Ball Bearing 6002LLU 211232-6		1	

Note

Interchangeability mark; <= means that the new part can be substituted for the current.

Implementation

HK1800: From Serial No. 46374

HK1810: From Serial No. 30116