


# TECHNICAL INFORMATION



74413

September, 2005

- Subject** ▶ Change of Impact Bolt
- For Models** ▶ HK1800, HK1800L, HK1810
- Country** ▶ All countries
- Description** ▶ Impact bolt has been changed as illustrated below.



## Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
HK1800: 033 HK1800L: 079 HK1810: 032	Impact Bolt ----- 321856-1		1	←	Impact Bolt ----- 324680-1		1	

### Interchangeability mark ;

The arrow ← means that the new part can be substituted for the current.

## Implementation

### For Italy

HK1800 and HK1810: From October 2005 production

### For all countries except Italy

HK1800 and HK1810: As soon as the current parts in stock run out  
(HK1800L: Discontinued since April 1993)