


# TECHNICAL INFORMATION



62491  
(Page 1 of 2)

- Subject** ▶ Change of Cord Guard
- For Models** ▶ HK1810, HM0810B, HM1303, HM1303B, HM1500, HM1500B, HR2010, HR5000, 9067L, 9069
- Country** ▶ See below.
- Description** ▶ Cord Guard has been changed as illustrated below to increase its flexibility.  
**Note: This Technical Information applies to machines manufactured in MJ (Makita Japan) only.**



## Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	For country
See note 1 below.	Cord Guard 682505-8		1	←	Cord Guard 682568-4		1	See note 3 below.
See note 1 below.	Cord Guard 682540-6		1	←	Cord Guard 682568-4		1	See note 4 below.

## Note

1. Item No. of Cord Guard

For Model	HK1810	HM0810B	HM1303	HM1303B	HM1500	HM1500B	HR2010	HR5000	9067L	9069
Item No.	070	075	011	011	044	044	054	111	028	028

(Note) Item No. may differ from country to country.

2. Interchangeability mark ; ← means that the new part is substituted for the current.

3. HK1810: Australia

HM1303: U.S.A., U.K.(110V/240V), Hong Kong, Philippines, Thailand, Vietnam, Australia, Guam, New Zealand

HM1303B: Canada, U.S.A., Mexico(120V), Brazil(127V/220V), Chile, U.K.(110V), Guam

HM1500: Canada, U.S.A., Panama, Philippines, Thailand, Vietnam, Guam

HM1500B: U.S.A., Mexico(120V), Panama, Brazil, Chile, Guam

HR2010: Brazil(127V/220V), Chile, Guyana, Paraguay, Peru, Uruguay, Austria, France, Cyprus(240V), Germany, Italy, Netherlands, Spain, Sweden, Reunion, U.K., Algeria, South Africa, Syria, North Korea, Philippines, Thailand, Vietnam, Australia, New Zealand

HR5000: Canada, U.S.A., Mexico(220V), Brazil(120V/220V), Chile, Saudi Arabia, Philippines, Thailand

9067L: U.S.A., Panama, Bolivia, Chile, Paraguay, Peru, Uruguay, Guam

9069: Bolivia, Chile, Paraguay, Peru, Uruguay, Saudi Arabia(127V), Syria

## Note

4. HK1810: Austria, France, Germany, Italy, Netherlands, Reunion, Spain, Sweden, Algeria, South Africa  
HM0810B: Austria, France, Germany, Italy, Netherlands, Reunion, Russia, Spain, Algeria, Bhutan  
HM1303: Austria, France, Germany, Italy, Netherlands, Spain, Sweden, Reunion, U.K.(240V), Kuwait, Algeria,  
South Africa, Bhutan, China, Hong Kong, South Korea  
HM1303B: Argentina, Austria, France, Germany, Italy, Netherlands, Reunion, Spain, Sweden, Algeria  
HM1500: Austria, France, Germany, Italy, Netherlands, Reunion, Russia, Spain, Algeria  
HM1500B: Austria, Germany, Spain  
HR2010: Malaysia, Singapore  
HR5000: Austria, France, Germany, Italy, Spain, Bhutan  
9067L: Argentina  
9069: Dominica, Saudi Arabia(220V), Canary Islands, Egypt, New Caledonia

## Implementation

- HK1810: From serial No. 67629E (Nov., 2000)  
HM0810B: From serial No. 43901E (Nov., 2000)  
HM1303: From serial No. 38675E (Nov., 2000)  
HM1303B: From serial No. 10023E (Nov., 2000)  
HM1500: From serial No. 41352E (Nov., 2000)  
HM1500B: From serial No. 11362E (Dec., 2000)  
HR2010: From serial No. 114499E (Nov., 2000)  
HR5000: From serial No. 55083E (Nov., 2000)  
9067L: From serial No. 55391E (Feb., 2001)  
9069: From serial No. 111108E (Dec., 2000)