

TECHNICAL INFORMATION



74339


September 2005

Subject ▶ Change of Crank Housing, etc.

For Models ▶ HM1801, HM1810

Country ▶ All countries

Description ▶ Crank housing of HM1801 and HM1810 has been changed as illustrated below.
Crank box of HM1810 has also been changed.



Interchangeability(I/C)

For HM1801

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
031	Crank housing 317903-4		1	Yes	Crank housing 318027-9		1	

For HM1810

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
031	Crank housing 317903-4		1	No	Crank housing 318027-9		1	Interchangeable as a set
066	Crank Box 317900-0		1	←	Crank Box 318028-7		1	

Interchangeability mark ;

The arrow ← means that the new part can be substituted for the current.

Implementation

Canada, USA, Brazil(110V), Mexico, Panama, UK(110V): To be implemented around October 2005 production
Remaining countries: Around the middle of August 2005 production