


Subject	▶ Addition of Adhesive and Modification of Gear Housing Cover Complete
For Models	▶ HP2050, HP2050F, HP2051, HP2051F
Country	▶ All countries
Description	▶ See below.

1. Adhesive (Three Bond 1327) has been applied to threaded portion of Bearing retainer.



2. Shape of Gear housing cover complete has been modified as shown below.

▶ Current	▶ New
	 This portion of Gear housing cover complete has been cut off for distinction.

## Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
—	—				Three Bond 1327 (50g) 045032-0A		0.1g	
024	Gear Housing Cover Complete 153364-2		1	←	Gear Housing Cover Complete 153620-0		1	

## Interchangeability mark ;

The arrow ← means that the new part can be substituted for the current.

## Implementation

From Mar., 2003 production.