



- Subject** ▶ Change of Spur Gear 29-37
- For Models** ▶ HP2070, HP2070F, HP2071, HP2071F
- Country** ▶ All countries
- Description** ▶ Spur Gear 29-37 has been changed as illustrated below.

▶ Current	▶ New
<p>sintered gear</p>  <p>Spur Gear 29-37 (227030-8)</p>	<p>machined gear</p>  <p>Spur Gear 29-37 (227119-2)</p>

Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
021	Spur Gear 29-37 227030-8		1	←	Spur Gear 29-37 227119-2		1	The current Spur Gear 29-37 (Part No. 227030-8) can be used for the repair of models HP2050, HP2050F, HP2051, HP2051F.

Interchangeability mark ;

The arrow ← means that the new part can be substituted for the current.

Implementation

From April, 2004 production