


# T ECHNICAL INFORMATION



58886B

- Subject** ▶ Change of O Ring 97
- For Models** ▶ HR3501, HR3510, HR3511, HR3520, HR3520B, HR3521
- Country** ▶ All countries
- Description** ▶ O Ring 97 has been replaced with Seal Ring for quick repair.



## Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
HR3501; 042	O Ring 97		1	Yes	Seal Ring		1	
HR3510; 042	213854-8				421688-7			
HR3511; 042								
HR3520; 031								
HR3520B; 030								

## Implementation

- HR3501 : Discontinued since Jan.,1983
- HR3510 : Discontinued since July,1988
- HR3511 : Discontinued since July,1988
- HR3520 : From serial No.140470E (July,1999)
- HR3520B : From serial No.32787E (July,1999)
- HR3521 : Discontinued since Aug.,1991