


T ECHNICAL INFORMATION



58886C

- Subject** ▶ Change of O Ring 113
- For Models** ▶ HR5000, HR5000K
- Country** ▶ All countries
- Description** ▶ O Ring 113 has been replaced with Seal Ring for quick repair.



Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
HR5000; 029 HR5000K; 029	O Ring 113 213906-5		1	Yes	Seal Ring 421690-0		1	

Implementation

HR5000 : From serial No.50947E (July,1999)
 HR5000K : From serial No.56477E (July,1999)