

Subject ▶ Changes on piston, striker, rings, herical gear and ball bearing

For Models ▶ HR5000,HR5000K (50mm Rotary Hammers)

Description ▶ As illustrated below, several parts have been changed to reduce damage for herical gear.

	▶ Current	▶ New
Piston Rings	<p>Piston Ring 40 (Resin) Inner Ring 36 (Metal) Piston</p>	<p>O Ring 32 Piston</p>
Striker Rings	<p>Piston ring 40 Striker Inner ring 36</p>	<p>O Ring 32 Striker</p>

Interchangeability(I/C)

Item No.	Current part	Q'ty	I/C	New part	Q'ty	Note
13	Piston 321441-0	1	No	Piston 323750-3	1	The current can be used for HM1200, HM1200B, HM1200K HM1201, HM1211, HM1211B.
7	Striker 322155-4	1	No	Striker 323751-1	1	Interchangeable as aaa set
8	Piston Ring 40 412049-2	2	No	O Ring 32 213481-1	2	The current can be used for HM1200, HM1200B, HM1200K HM1201, HM1211, HM1211B.
	Inner Ring 36 341862-0	1				
	Inner Ring 36 412080-8	1				

Implementation

HR5000 : From serial No. 40695E (July, 1997)

HR5000K : From serial No. 45316E (July, 1997)

Note

Only herical gear will be changed from Sep.,1997