

T ECHNICAL INFORMATION

- Subject** ▶ Change of Hex.Socket Head Bolt Which Fixes Shoe Plate to Shoe Supporter
- For Models** ▶ DK1020, DK1021, JR140D, JR180D, JR3020, JR3030, JR3030T
(DK1020 and DK1021 are cordless tool kits which include JR180D.)
- Country** ▶ JR3020 ; All countries
JR140D, JR180D, JR3030, JR3030T ; All countries except European countries
DK1020, DK1021 ; Canada and U.S.A.
- Description** ▶ In order to prevent the threads of the subject bolt from touching the hole of Shoe Plate and coming worn down;
 - 1) The bolt has been changed as illustrated below.
 - 2) JR140D, JR180D, JR3030T, DK1020, DK1021; A Spring Washer 5 has been added.
JR3020, JR3030; The position of Spring Washer 5 has been changed as illustrated below.

	▶ Current	▶ New
JR140D JR180D JR3030T DK1020 DK1021		
JR3020 JR3030		

Interchangeability(I/C)

Item No.	Current part	Q'ty	I/C	New part	Q'ty	Note
JR140DW; 021 JR180DW; 021 JR3030T; 002	Hex. Socket Head Bolt M5x50 ----- 922911-8	1	No	Hex. Socket Head Bolt M5x50 ----- 266241-0	1	↑ JR140D, JR180D JR3030T, DK1020, DK1021 ↓
JR140DW; 078 JR180DW; 078 JR3030T; 084				Spring Washer 5 ----- 942101-7	1	
JR3020; 002 JR3030; 016	Hex. Socket Head Bolt M5x45 ----- 922907-9	1	No	Hex. Socket Head Bolt M5x45 ----- 266242-8	1	JR3020, JR3030 (see "Note" below)

Note

Regarding JR3020 and JR3030, the current bolt and the new one is interchangeable when Spring Washer 5 is shifted from the bolt side to the nut side as illustrated above.
See next page for "Implementation".

Implementation

Machines manufactured in U.S.A.

JR140D : Around Dec.,1999

JR180D : Around Dec.,1999

JR3020 : Around Sep.,1999

JR3030 : Around Mar.,2000

JR3030T : Around Nov.,1999

Machines manufactured in Japan

JR3020 : From serial No.42023E (Sep.,1999)

JR3030 : From serial No.1609E (Oct.,1999)

JR3030T : From serial No.4338E (Oct.,1999)