


T ECHNICAL INFORMATION

- Subject** ▶ Change on Outer Flange
- For Models** ▶ LC1230, LC1210
- Country** ▶ All countries
- Description** ▶ Outer Flange has been modified as illustrated below.



Interchangeability(I/C)

| Item No. | Current part | | Q'ty | I/C | New part | | Q'ty | Note |
|-------------|-----------------|--|------|-----|-----------------|--|------|------|
| LC1230: 052 | Outer Flange 69 | | 1 | ← | Outer Flange 69 | | 1 | |
| LC1210: 022 | 224309-8 | | | | 224379-7 | | | |

Interchangeability mark ;

The arrow ← means that the new part can be substituted for the current.

Implementation

LC1230 : To be informed later
 LC1210 : Discontinued since Jan., 2001