



TECHNICAL INFORMATION





68122

| | |
|--------------------|--|
| Subject | ▶ Change of Base and Chain |
| For Models | ▶ 2414B, 2414DB, 2414NB, 2416S, LC1200, LC1210, LC1230 |
| Country | ▶ All countries |
| Description | <p>▶ Regarding portable cut-offs 2414B, 2414DB, and 2414NB for Canada, U.S.A., Mexico and Panama;</p> <p>1) Base and Chain have been changed.</p> <p>2) M6x16 Hex. socket head bolt has been added.</p> <p>Also, Chain of metal cutting saws LC1200, LC1210 and LC1230 has been changed.</p> <p>Regarding all countries except for Canada, U.S.A., Mexico, and Panama, only Chain has been changed.</p> <p>See illustration below for the details.</p> |

Canada, U.S.A., Mexico, and Panama

| ▶ Current | ▶ New |
|--|---|
|  <p>Base (for 2414DB, 2414NB: 165230-1 for 2414B: 165307-2)</p> <p>Chain (282010-1)</p> |  <p>Base (for 2414DB, 2414NB: 165354-3 for 2414B: 165355-1)</p> <p>Chain (282016-9)</p> <p>M6x16 Hex. socket head bolt for 2414B, 2414DB, 2414NB (922323-5)</p> |

All countries except for Canada, U.S.A., Mexico, and Panama

| ▶ Current | ▶ New |
|---|---|
|  <p>Chain (282010-1) It consists of eight rings.</p> |  <p>Chain (282016-9) It consists of ten rings.</p> |

Interchangeability(I/C)

Canada, U.S.A., Mexico, and Panama

| Item No. | Current part | | Q'ty | I/C | New part | | Q'ty | Note |
|-----------------------------------|-------------------|--|------|-----|--|--|------|--|
| 079 | Base 165230-1 | | 1 | ← | Base 165354-3 | | 1 | For 2414DB, 2414NB |
| 083 | Base 165307-2 | | 1 | ← | Base 165355-1 | | 1 | For 2414B |
| 2414B, 2414DB: 087 2414NB: 088 | | | | | Hex. Socket Head Bolt M6x16 922323-5 | | 1 | For 2414B, 2414DB, 2414NB |
| See below. | Chain 282010-1 | | 1 | ← | Chain 282016-9 | | 1 | For 2414B, 2414DB, 2414NB, 2416S, LC1200, LC1210, LC1230 |

All countries except for Canada, U.S.A., Mexico, and Panama

| Item No. | Current part | | Q'ty | I/C | New part | | Q'ty | Note |
|------------|-------------------|--|------|-----|-------------------|--|------|--|
| See below. | Chain 282010-1 | | 1 | ← | Chain 282016-9 | | 1 | For 2414B, 2414DB, 2414NB, 2416S, LC1200, LC1210, LC1230 |

Interchangeability mark ;

The arrow ← means that the new part is substituted for the current.

Item No. of Chain

| 2414B | 2414DB | 2414NB | 2416S | LC1200 | LC1210 | LC1230 |
|-------|--------|--------|-------|--------|--------|--------|
| 084 | 058 | 055 | 095 | 027 | | 028 |

Implementation

2414B, 2414DB, 2414NB: From Jul., 2003 production.
2416S, LC1230: As soon as the current parts run out.

LC1200: Discontinued since May, 1995.
LC1210: Discontinued since Jan., 2001.