


T ECHNICAL INFORMATION



88615
March 2010

- Subject** ▶ Change of Front Arm Complete
- For Models** ▶ LS1216, LS1216L
- Country** ▶ All countries
- Description** ▶ Front arm complete has been modified to prevent accumulation of cutting chips.



Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
157	Front Arm Complete 140154-2		1	←	Front Arm Complete 140711-6		1	

Interchangeability mark;

The arrow ← means that the new part can be substituted for the current.

Implementation

MJ plant LS1216: From serial No. 2706E (February 2010)

MJ plant LS1216L: From serial No. 1199E (April 2010)

MCA plant: From March 2010 production

MKC and MME plants: From initial production