

TECHNICAL INFORMATION



70635



Subject ▶ Change of Screw M5x15 and Carton Box

For Models ▶ RP0910, RP1110C

Country ▶ All countries

Description ▶ M5x15 Screw and Carton box have been changed as shown below.

(1) M5x15 Screw has been replaced by M5x14 Thumb screw.

| ▶ Current | ▶ New |
|--|--|
|  Screw M5x15 (265740-9) |  Thumb Screw M5x14 (265720-5) |

(2) Color Carton box has been replaced by Brown Carton box.

Interchangeability(I/C)

| Item No. | Current part | | Q'ty | I/C | New part | | Q'ty | Note |
|----------|-------------------------|--|------|-----|-------------------------------|--|------|-------------|
| 074 | Screw M5x15 265740-9 | | 3 | Yes | Thumb Screw M5x14 265720-5 | | 3 | |
| C01 | Carton Box 843866-3 | | 1 | Yes | Carton Box 846701-4 | | 1 | For RP0910 |
| C01 | Carton Box 843867-1 | | 1 | Yes | Carton Box 846702-2 | | 1 | For RP1110C |

Implementation

For replacement of Screw

RP0910: From serial No. 7170E (April, 2004)

RP1110C: From serial No. 19249E (April, 2004)

For replacement of Carton box

After Color Carton boxes run out of our stock.