

- Subject** ▶ Change of Thumb Nut, Half Nut and Compression Spring for Stopper Pole
- For Models** ▶ RP0910, RP1100, RP1101, RP110C
- Country** ▶ All countries
- Description** ▶ Half Nut, Thumb Nut M14 and Compression Spring 5 have been replaced by Half Nut Complete in order to avoid dropping them down or missing.

► Current	► New
<p>Thumb Nut M14</p> <p>Half Nut</p> <p>Compression Spring</p>	<p>(Thumb Nut M14)</p> <p>(Half Nut)</p> <p>(Cap 15)</p> <p>Half Nut Complete</p>

Interchangeability(I/C)

For Model RP0910, RP110C

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
054	Half Nut 323858-3		1	No	Half Nut Complete 153476-1		1	Interchangeable as a set
086	Compression Spring 5 231419-4		1					
087	Thumb Nut M14 252644-4		1					

For Model RP1100, RP1101

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
038	Half Nut 324104-7		1	No	Half Nut Complete 153475-3		1	Interchangeable as a set
035	Compression Spring 5 231419-4		1					
039	Thumb Nut M14 252644-4		1					

Implementation

From July 2002 production