

TECHNICAL INFORMATION



87954
January 2010

Subject ▶ Correction of Ball Bearing 6801LLB

For Models ▶ TD021D

Country ▶ All countries

Description ▶ Ball bearing 6801LLB has been replaced by Ball bearing 6801LLU.

Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
006, 021	Ball Bearing 6801LLB ----- 210112-3		2	Yes	Ball Bearing 6801LLU ----- 210108-4		2	

Implementation

From around February 2010 production