


- Subject** ▶ 1) Change of Inlet (for 4072D and 4073D only)
2) Change of installing method of Packing
- For Models** ▶ 4072D, 4073D, 4093D
- Country** ▶ All countries
- Description** ▶ To prevent dust in Dust Bag from falling out;
1) Brim has been added to Inlet as illustrated below. (for 4072D and 4073D only)
2) Packing has been installed upside down so that the upper part of valve will open as illustrated below.



Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
4072DW : 023 4073DW : 025	Inlet 416031-3		1	←	Inlet 417686-7		1	

Note

Interchangeability mark ; ← means that the new part is substituted for the current.

Implementation

To be informed later