


**Subject** ▶ Change of Ball Bearing and removal of Ring 19

**For Models** ▶ 4322 4323 4322M 4323M

**Description** ▶ As illustrated below, Ball Bearing has been changed and Ring 19 has been removed.



## Note

Part Number of Armature Ass'y remains the same. Please remove Ring 19 when you use New Armature Ass'y.

## Interchangeability(I/C)

Item No.	Curret part	Q'ty	New part	Q'ty	I/C	Note
032	Ball Bearing 607LLB 211021-9	1	Ball Bearing 627LLB 210025-8	1	No	Interchangeable as a set ↑ ↓
033	Ring 19 257216-0	1				

## Implementation

4322:From Dec, 1998

4323:From Dec, 1998

4322M:From Dec, 1998

4323M:From Dec, 1998