


TECHNICAL INFORMATION

- Subject** ▶ Change of Ball Bearing
- For Models** ▶ 5603R, 5703R
- Country** ▶ All countries
- Description** ▶ As illustrated below, the Ball Bearing on the rear side of the armature shaft has been changed for further durability.



▶ Current	▶ New
Ball Bearing 608LLB (Part No.211031-6)	Ball Bearing 608DDW (Part No.210005-4)

Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
5603R: 032 5703R: 033	Ball Bearing 608LLB ----- 211031-6		1	←	Ball Bearing 608DDW ----- 210005-4		1	

Note

Interchangeability mark ; ← means that the new part is substituted for the current.

Implementation

5603R : From serial No.58762G (Nov.,1999)
5703R : From serial No.143766G (Nov.,1999)