

Subject ▶ Change of Housing Set and screws

For Models ▶ 6172D,6172DW(Cordless Driver Drill)


Description ▶ As illustrated below, Housing Set and screws have been changed.

1)Change of screws

Screws have been chaged to self-tapping screws.

2)Change of Housing Set

Bosses of Housing R for screws have been changed.



Interchangeability(I/C)

Item No.	Current part	Q'ty	I/C	New part	Q'ty	Note
2	Housing Set 182407-3	1	No	Housing Set 182828-9	1	Manufactured in Japan
2	Housing Set 182779-6	1	No	Housing Set 182828-9	1	Manufactured in U.K.
27	Pan Head Screw M4X22 911143-2	8	No	Tapping Screw Flange PF 4X18 266121-0	8	Interchangeable as a set

Implementation

From Mar.,1996 (Manufactured in U.K.)

Discontinued since Oct.,1993 (Manufactured in Japan)