



TECHNICAL INFORMATION



60167

- Subject** ▶ Addition of Gear Complete Repairing Set
- For Models** ▶ 6409, 6410
- Country** ▶ All countries
- Description** ▶ To prevent the chuck from wobbling after replacing Gear Complete, Gear Complete Repairing Set (including Steel Ball 3.5 and Pin 4) has become available.

▶ Current	▶ New
<p>Gear Complete</p>  <p>Steel Ball 3.5</p> <p>Pin 4</p>	<p>Gear Complete Repairing Set (including Steel Ball 3.5 and Pin 4)</p> 

Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part	Q'ty		Note
009	Gear Complete 153245-0		1	←	Gear Complete Repairing Set 193050-3	1		
007	Steel Ball 3.5 216001-0		1					
006	Pin 4 256251-5		1					

Note

Interchangeability mark ; ← means that the new part is substituted for the current.

Implementation

Ready to receive your order since Jan., 2000