


Subject ▶ Change of Anvil

For Models ▶ 6905H, SI100

Country ▶ All countries

Description ▶ As illustrated below, grinding work has been added onto the circumferences of hole after heat treatment.



Interchangeability(I/C)

SI100

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
017	Anvil 322503-7		1	←	Anvil 324357-8		1	For all countries

6905H

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
015	Anvil 322503-7		1	←	Anvil 324357-8		1	For all countries except Canada, U.S.A., Mexico, Panama
015	Anvil 322504-5		1	←	Anvil 324358-6		1	For Canada, U.S.A., Mexico, Panama

Interchangeability mark ;

The arrow ← means that the new part is substituted for the current.

Implementation

From Oct.,2002 production.