



Subject ▶ Change on spindle and screw M6, and discontinuance on ring spring 6

For Models ▶ 8412DH/DWH (Cordless Percussion-Driver Drill)

Description ▶ 1. The current type spindle has an internal hexagon. But the new type spindle will have no internal hexagon.



2. The screw M6 will be changed in length.



3. The ring spring 6 will be discontinued.

Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
15	Spindle 322621-1		1	No	Spindle 322713-6		1	Interchangeable as a set
12	Screw M6x32 251456-2		1	No	Screw M6x22 251425-3		1	
14	Ring spring 6 231959-2		1					

Implementation

8412DH : From serial No. 500030E

8412DWH: From serial No. 1754E

Re: Model 8412DWH with serial Nos. 1154E - 1753E for Germany

They have the current type spindle but their spindle have no internal hexagon. They do not have ring spring 6.