



- Subject** ▶ Change on lock nut
- For Models** ▶ 9029, 9029S, 9039, 9039S, 9027, 9027S, 9027L, 9037 and 9037S (Disc Grinders)
- Note** ▶ This information applies to DIN-type countries.
- Description** ▶ As illustrated below, lock nut has been changed against excessive tightening of lock nut.

	▶ Current	▶ New
Lock Nut	 Lock Nut 14—45	 Lock Nut Assembly

### Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
28	Lock Nut 14-45 224543-0		1	<=	Lock Nut Set 192567-3		1	The current part can be used for 9005B, etc.

### Note

Interchangeability mark; <= means that the new part can be substituted for the current.  
Do not use the current part for 9029, etc.

### Implementation

9029: From serial No. 82414E  
 9029S: From serial No. 65315E  
 9039: From serial No. 15404E  
 9039S: From serial No. 8685E  
 9027: From serial No. 40330E  
 9027S: No machine applicable to this modification.  
 9027L: No machine applicable to this modification.  
 9037: No machine applicable to this modification.  
 9037S: No machine applicable to this modification.  
 \*All models are to be discontinued in June, 1996.