

# T ECHNICAL INFORMATION



71074

**Subject** ▶ Change of Steel Plate

**For Models** ▶ 9910, 9911

**Country** ▶ (For 9910) Bolivia, Dominica, Guyana, Paraguay, Peru, Uruguay, Canary Islands, Cyprus, Turkey, Saudi Arabia, Syria, Algeria, Congo, Gabon, Morocco, Reunion, Indonesia, Malaysia, North Korea, Philippines, Singapore, Thailand, Taiwan, Vietnam, Australia, New Zealand, Guam, New Caledonia, Tahiti

(For 9911) Argentina, Bolivia, Dominica, Gabon, Guyana, Paraguay, Peru, Uruguay, Congo, Canary Islands, Kuwait, Saudi Arabia, Syria, Turkey, Algeria, Morocco, Malaysia, Reunion, South Africa, Indonesia, North Korea, Philippines, Singapore, Thailand, Vietnam, Guam, Australia, New Zealand, New Caledonia, Tahiti

**Description** ▶ Surface treatment of Steel plate has been changed as shown below.

▶ Current	▶ New
Applying anti-rust oil on the steel plate	Using black-oxidized steel plate

## Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
052	Steel Plate 344586-7		1	Yes	Steel Plate 345503-0		1	

## Implementation

To be implemented from July, 2004 production