

# TECHNICAL INFORMATION




89500  
August 2010

**Subject** ▶ Change of Switch Lever

**For Models** ▶ AT-3623, BBC231U

**Country** ▶ All countries

**Description** ▶ Switch lever has been changed as illustrated below to ensure the clearance between Switch lever and Plunger.  
When replacing the current Switch of Product Nos. 1001E to 1890E with the new one, replace the new Switch lever with the new one at the same time.



## Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
009	Switch Lever 451573-0		1	←	Switch Lever 452594-5		1	
013	Switch TGR3-2 650629-8		1	See above.	Switch TGR3-2 650629-8		1	See above. The part No. remains the same.

### Interchangeability mark;

The arrow ← means that the new part can be substituted for the current.

## Implementation

From July 2010 production