

TECHNICAL INFORMATION



99801
April 2013

- Subject** ▶ Change of Screws
- For Models** ▶ DOLMAR: SP-1815
Makita: BVF104, BVF154
- Country** ▶ All countries
- Description** ▶ Screw for the following item numbers has been changed.

Interchangeability(I/C)

Model No.	Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note	
SP-1815	008	Screw M5		3	Yes	Screw M5		3	For fastening Battery housing	
BVF104		-----				-----				
BVF154		0140059160				0140059260				
SP-1815	028	Screw M5		3	Yes	Screw M5		3	For fastening Holder pump	
BVF104	026					-----				-----
BVF154	028					0140059160				0140059260
SP-1815	029	Screw M5		4	Yes	Screw M5		4	For fastening Cushion	
BVF104	027					-----				-----
BVF154	029					0140059160				0140059260

Implementation

From February 2013 production