

TECHNICAL INFORMATION



Y05612
June 2010

Subject ▶ Change of Cushion and Band Complete

For Models ▶ BVF104, BVF154, SP1815

Country ▶ All countries

Description ▶ Cushion and Band complete have been changed.

Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
BVF154, SP1815: 030 BVF104: 028)	Cushion ----- 6954013000		1	Yes	Cushion ----- 6954025000		1	BVF104, BVF154, SP1815
001	Band Comp ----- 6954016000		1	Yes	Band Ass'y ----- 6954026000		1	BVF104

Implementation

BVF104, BVF154Z, SP1815: Already implemented since March 2010 production

BVF154RF: Already implemented since February 2010 production