


T ECHNICAL INFORMATION

- Subject** ▶ Change of Ball Bearing 608LLB
- For Models** ▶ DA3010, DA3010F, DA3011, DA3011F
- Country** ▶ All countries
- Description** ▶ Ball bearing 608LLB has been replaced by Ball bearing 608ZZ as illustrated below.



Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
004, 016	Ball Bearing 608LLB 211031-6	2	Yes	Ball Bearing 608ZZ 210029-0	2			

Implementation

From January, 2005 production.