


Subject ▶ Change on DC Motor

For Models ▶ DA391D, DA391DW, DA390D, DA390DW (Cordless angle drills)

Description ▶ In order to conform to UL Standards, the current motor has been replaced by the new motor which is equipped with an inside cooling fan. This information applies to all the countries and areas.



Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
14	DC motor 629595-0		1	Yes	DC motor 629623-1		1	The current motor has been discontinued.

Implementation

DA391D: From serial No. 637559E
DA391DW: From serial No. 59587E
DA390D: Discontinued since Oct., 1993
DA390DW: Discontinued since Oct., 1993