

# TECHNICAL INFORMATION



96858

November 2012

- Subject** ▶ Change of Part number for Piston clip and Ball bearing 6001
- For Models** ▶ Makita: DCS230T, DCS231T, DCS232T  
DOLMAR: PS-220TH, PS-221TH, PS-222TH
- Country** ▶ All countries
- Description** ▶ The part numbers for Piston clip and Ball bearing 6001 have been changed for parts unification.  
The actual parts remain the same.

## Interchangeability(I/C)

| Item No. | Current part      |  | Q'ty | I/C | New part          |  | Q'ty | Note |
|----------|-------------------|--|------|-----|-------------------|--|------|------|
| 106, 111 | Piston clip       |  | 1    | Yes | Clip              |  | 1    |      |
|          | 324529-5          |  |      |     | 233976-8          |  |      |      |
| 104, 105 | Ball bearing 6001 |  | 1    | Yes | Ball bearing 6001 |  | 1    |      |
|          | 210101-8          |  |      |     | 210113-1          |  |      |      |

## Implementation

After the current parts in stock are cleared.