

# TECHNICAL INFORMATION



A2821  
February 2014

**Subject** ▶ Change of Gear assembly

**For Models** ▶ BDF446, BDF456, DDF456, LXFD01, XFD01,  
BHP446, BHP456, DHP456, LXPH01, LXPH02, XPH01

**Country** ▶ All countries

**Description** ▶ Gear assembly has been changed to comply with the standards.  
**Note:** The appearance and the actual motor specifications remain the same.

## Interchangeability(I/C)

Item No.	Current part	Q'ty	I/C	New part	Q'ty	Note
011	Gear assembly 125831-7	1	←	Gear assembly 126459-4	1	BDF446, BDF456, DDF456, LXFD01, XFD01
011	Gear assembly 125848-0	1	←	Gear assembly 126460-9	1	BHP446, BHP456, DHP456, LXPH01, LXPH02, XPH01

### Interchangeability mark ;

The arrow ← means that the new part can be substituted for the current.

## Implementation

BDF446, BHP446, LXPH02: After the current parts in stock are cleared.

Others: From January 2014 production