


# TECHNICAL INFORMATION



A4604  
June 2014

- Subject** ➤ Change of M4x17 H.L. Socket head bolt
- For Models** ➤ Makita: EN4950H, EN4950HG, EN5950SH, EN5950SHG, EN7350SH  
DOLMAR: MH-246.4 D, MH-246.4 DS
- Country** ➤ All countries
- Description** ➤ H.L. Socket head bolt has been changed to widen the adjustable range of the engine speed.



**Note:** If replacing the current part (part No. 266887-2) with a new part (part No. 266927-6), replace it together with Holder (part No. 346730-2).

## Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
237	H.L. Socket head bolt M4x17 266887-2		1	No	H.L. Socket head bolt M4x20 266927-6		1	Interchangeable as a set
240	Holder 346730-2		1	No	Holder 346730-2		1	

## Implementation

From initial production at MKC plant