


- Subject** ▶ Change of Motor Housing Complete
- For Models** ▶ HK1800, HK1810, HK1800L
- Country** ▶ All countries except Asia
- Description** ▶ Motor housing complete has been changed as illustrated below.



Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
HK1800: 054 HK1810: 053 HK1800L: 100	Motor Housing Complete 157553-1		1	←	Motor Housing Complete 157553-1		1	The part No. remains the same.
HK1800: 908 HK1810: 907 HK1800L: 904					Makita Label 819063-3		1	

Interchangeability mark ;

The arrow ← means that the new part is substituted for the current.

Note

Motor housing complete for replacement don't come with Name plate or Makita label.

Implementation

- HK1800: From serial No. 64616E (Apr., 2003)
- HK1810: From serial No. 86010E (Apr., 2003)
- HK1800L: Discontinued since Apr., 2003