





Subject ▶ Changes on barrel complete and barrel cover

For Models ▶ HM0810, HM0810B, HM0811, HM0821

Description ▶ As illustrated below, two parts have been changed for improvement in strength of barrel.

	▶ Current	▶ New
Barrel Complete	 <p>ø48</p>	 <p>ø50</p> <p>Outer diameter of the area indicated in the illustration becomes thicker.</p>
Barrel Cover	<p>Sectional view</p> 	<p>Sectional view</p>  <p>Inner diameter of barrel cover becomes wider to follow the change of barrel complete. Outer diameter remains the same.</p>

Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part	Q'ty		Note
4	Barrel Complete 151413-9		1	No	Barrel Complete 151457-9		1	Interchangeable as a set
1	Barrel Cover 421196-8		1	No	Barrel Cover 421541-7		1	

Implementation

HM0810 : From serial No.290724E
 HM0810B : From serial No.24864E
 HM0821 : Discontinued since June, 1991
 HM0811 : Discontinued since Apr.,1989