

# T ECHNICAL INFORMATION





57739,  
57890

**Subject** ▶ Change of Strain Relief

**For Models** ▶ HM1303, HM1303B, HM1500, HM1800, HR2400, JN1601,  
1100, 1911B, 2414B, 3612, 3612C, 4101R, 4402, 5103R, 5143R, 5900B,  
6904VH, 6905H, 6950, 8406C, 9005B, 9006B, 9046, 9047, 9049, 9901

**Country** ▶ Austria, France, Germany, Italy, Nrtherlands, Spain, U.K.,  
Canarias Islands, Russia, Sweden, Swizerland, Kuwait, Saudi Arabia, Turkey,  
Algeria, Congo, Egypt, Gabon, Morocco, Reunion, South Africa,  
Buhtan, Hong Kong, Indonesia, Malaysia, Mongolia, Singapore, South Korea,  
New Caledonia, Tahiti, The Commonwealth of Dominica

**Description** ▶ As illustrated below, Strain Relief has been changed.

▶ Current	▶ New
 10.0mm (Part No.687063-9)	 8.0mm (Part No.687052-4)

## Interchangeability(I/C)

Item No.	Current part	Q'ty	I/C	New part	Q'ty	Note
	Strain Relief 687063-9	1	←	Strain Relief 687052-4	1	

## Note

Interchangeability mark ; ← means that the new part is substituted for the current.

## Implementation

HM1303 : From serial No.22052E (Feb.,1999)  
 HM1303B : From serial No.6138E (Mar.,1999)  
 HM1500 : From serial No.30935E (Feb.,1999)  
 HM1800 : From serial No.14452E (Feb.,1999)  
 HR2400 : From serial No.239540E (Feb.,1999)  
 JN1601 : From serial No.35233E (Feb.,1999)  
 1100 : From serial No.796933E (Feb.,1999)  
 1911B : From serial No.236172E (Feb.,1999)  
 2414B : From serial No.159442E (Feb.,1999)  
 3612 : From serial No.70035E (Feb.,1999)  
 3612C : From serial No.36978E (Feb.,1999)  
 4101R : From serial No.12934E (Dec.,1998)  
 4402 : From serial No.2582E (May, 1999)  
 5900B : From serial No.1026454E (Apr.,1999)  
 6904VH : From serial No.53496E (Feb.,1999)  
 6905H : From serial No.76373E (Feb.,1999)  
 6950 : From serial No.8744E (June, 1999)  
 8406C : From your next order in/after June,1999  
 9005B : From your next order in/after June,1999  
 9006B : From your next order in/after June,1999  
 9046 : From serial No.42736E (Feb.,1999)  
 9047 : From serial No.41335E (Feb.,1999)  
 9049 : From serial No.54405E (June, 1999)  
 9901 : From serial No.178896E (Feb.,1999)