



T ECHNICAL INFORMATION



Y04112

- Subject** ▶ Change of Armature Assembly
- For Models** ▶ HR3000C, HR3550C, HR4500C
- Country** ▶ All countries
- Description** ▶ Sleeve has been added to Armature Assembly.
The Armature part no. remains same.

▶ Current	▶ New
 <p>Armature Assembly (Part No. and Item No. are as shown below): It has no sleeve.</p>	 <p>Armature Assembly (Part No. and Item No. are as shown below.)</p>

Interchangeability(I/C)

Item No.	Current part	Q'ty	I/C	New part	Q'ty	Note
114	Armature Assembly 100V 513515-3	1	←	Armature Assembly 100V 513515-3	1	For HR3000C
114	Armature Assembly 115V 513516-1	1	←	Armature Assembly 115V 513516-1	1	For HR3000C, HR3550C
114	Armature Assembly 220-240V 513518-7	1	←	Armature Assembly 220-240V 513518-7	1	
094	Armature Assembly 100V 516840-1	1	←	Armature Assembly 100V 516840-1	1	For HR4500C
094	Armature Assembly 115V 516841-9	1	←	Armature Assembly 115V 516841-9	1	
094	Armature Assembly 220-240V 516843-5	1	←	Armature Assembly 220-240V 516843-5	1	

Interchangeability mark ;

The arrow ← means that the new part can be substituted for the current.

Implementation

To be informed later