


Subject ▶ Change on Torsion Spring 20 and Lever.

For Models ▶ UM401DW,AM4024LC

Description ▶ Following changes have been made.
 1. The diameter of Torsion Spring : $\phi 1.3\text{mm} \Rightarrow \phi 1.6\text{mm}$.
 2. Addition of gutter on Lever.



Interchangeability(I/C)

Item No.	Current part	Q'ty	I/C	New part	Q'ty	Note
58	Torsion Spring 20 231628-5	1	No	Torsion Spring 20 231639-0	1	↕ Interchangeable as a set ↕
59	Lever 416198-7	1	No	Lever 416627-0	1	

Implementation

From: Dec.,1997.