

MODEL

**RB397, RB217**

BULLETIN NO.


RB397-MK1

Date of Change

Jan , 2011

In order to improve stability of brake parts for RB397 and RB217, three parts were changed (Rotary Pin, Plate A, Pin 2113). Also, Rotary Pin in the Brake Assembly was changed to new version.

If you change one of 3 parts to new version, please change the rest of 2 parts to new version, too. Old Plate A (RB11978) was glued to the Frame L, but please **DON'T GLUE** new Plate A(RB12236) to the Frame L. \*These parts are already used for RB397 and RB217.



Part No	Old		Interchangeability	New	
	Part Code	Description		Part Code	Description
116	RB12026	ROTARY PIN	Not	RB12238	Same as Old
123	RB70494	BRAKE ASSY	Not	RB70531	
141	RB11978	PLATE A	Not	RB12236	
127	FF52113	PIN 2113	Not	FF52114	PIN 2114