







SERVICE BULLETIN

MODEL	RB398/218	Aug 2016 Serial: 167*****
--------------	------------------	--

Subject: Parts change (TIP AXIS)

Below parts has been modified. Performance & durability of tools are same as previous version.

OLD				NEW			
Diagram No	38	Part Code	RB70377	Diagram No	38	Part Code	RB70675
Part Name	TIP AXIS B			Part Name	TIP AXIS B		
							
Diagram No	39	Part Code	RB10115	Diagram No	39	Part Code	FF31599
Part Name	KEY B			Part Name	PARALELL PIN 1599		
							
Diagram No	41	Part Code	RB12018	Diagram No	41	Part Code	RB12708
Part Name	TIP AXIS A			Part Name	TIP AXIS A		
							

OLD Version				NEW Version	
ITEM#	PART#	DESCRIPTION	SUPPLY	PART#	DESCRIPTION
38	RB70377	TIP AXIS B	While supply lasts	RB70675	TIP AXIS B
41	RB12018	TIP AXIS A		RB12708	TIP AXIS A
39	RB10115	KEY B	Yes	FF31599	PARALELL PIN 1599
Interchangeability: NO. Set Change Required					

Kit Code

OLD Version				NEW Version	
	PART#	DESCRIPTION	SUPPLY	PART#	DESCRIPTION
46	RB81176	TIP AXIS ASSY	While supply lasts	RB81274	TIP AXIS ASSY
Interchangeability: YES					