



- Subject** ▶ Change of O ring
- For Models** ▶ HM1202, HM1202C, HM1242C
- Country** ▶ All countries
- Description** ▶ For quick repairing, O ring 38 has been replaced by O ring 36.



## Interchangeability(I/C)

| Item No. | Current part          |  | Q'ty | I/C | New part              |  | Q'ty | Note |
|----------|-----------------------|--|------|-----|-----------------------|--|------|------|
| 030      | O ring 38<br>213508-7 |  | 1    | Yes | O ring 36<br>213510-0 |  | 1    |      |

## Implementation

HM1202 : From serial No. 2566E (Oct., 1999)  
 HM1202C: From serial No. 7055E (Nov., 1999)  
 HM1242C: From serial No. 1001E (Nov., 1999)