

TECHNICAL INFORMATION



74488


September 2005

Subject ▶ Change of Connecting Rod and Ring 10

For Models ▶ HM1810

Country ▶ All countries

Description ▶ Connecting rod, Needle roller bearing 1010 and Ring 10 have been replaced by Connecting rod complete and Spacer as illustrated below.
The connecting rod complete consists of connecting rod and needle bearing 1012.
However, they can not be supplied respectively for repair.



Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
064	Connecting Rod 324535-0		1	No	Connecting Rod Complete 154946-3		1	Interchangeable as a set
063	Needle Roller Bearing 1010 212075-9		1					
071	Ring 10 257267-3		1	No	Spacer 331718-5		1	

Implementation

From serial No. 3448E (September 23, 2005)