


T ECHNICAL INFORMATION



58886A

- Subject** ▶ Change of O Ring 100
- For Models** ▶ HR3800, HR3811, HR3850, HR3850B, HR3850K, HR3851
- Country** ▶ All countries
- Description** ▶ O Ring 100 has been replaced with Seal Ring for quick repair.



Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
HR3800; 032	O Ring 100		1	Yes	Seal Ring		1	
HR3811; 032	213853-0				421689-5			
HR3850; 035								
HR3850B; 035								
HR3850K; 035								
HR3851; 035								

Implementation

- HR3800 : Discontinued since July, 1988
- HR3811 : From serial No.13507E (Aug.,1999)
- HR3850 : From serial No.77249E (Aug.,1999)
- HR3850B : From serial No.44696E (Aug.,1999)
- HR3850K : From serial No.27621E (Aug.,1999)
- HR3851 : From serial No.50724E (Aug.,1999)